

T	Ţ

L Number	Hits	Search Text	DB	Time stamp
3	4	(("6333790") or ("6631008")).PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/04/20 09:55
8	38993	ASIC	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/04/20 12:44
9	74	printer\$5 near2 controller\$5 with ASIC\$2	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/04/20 12:45
10	42	(printer\$5 near2 controller\$5 with ASIC\$2) and @ad<20000929	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/04/20
11	2	("6113208").PN.	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/04/20 14:27
12	o	(CRC\$4 with (printer\$5 near2 control\$5 near2 (program\$5 softwar\$5 firmwar\$5)))	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/04/20 14:28
13	0	(CRC\$4 same (printer\$5 near2 control\$5 near2 (program\$5 softwar\$5 firmwar\$5)))	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/04/20 14:28
14	2	("6665089").PN.	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/04/20 14:44
15	5448	(358/1.15).ccls.	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/04/20 14:44
16	136	(printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) and (compatibl\$5	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/04/20 14:45
17	28	<pre>integrit\$5 complianc\$5) ((358/1.15).ccls.) and ((printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) and (compatibl\$5</pre>	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 14:45
18	11) and ((printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) and (compatibl\$5 integrit\$5 complianc\$5))) and	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 14:45
-	229	<pre>@ad<20000929 (printer\$5 near3 controller\$5) with (IC\$2 integrat\$5 near2 circuit\$5)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/04/19 13:25



-	133		USPAT;	2004/04/19
		(IC\$2 integrat\$5 near2 circuit\$5)) and	US-PGPUB;	13:30
		@ad<20000929	EPO; JPO;	
			DERWENT;	
			IBM TDB	
-	21	(printer\$5 near2 control\$5) same (updat\$4	USPAT;	2004/04/19
		upgrad\$5 install\$5 replac\$5) same	US-PGPUB;	16:51
		(printer\$5 near2 (driver\$5 program\$5	EPO; JPO;	
		software\$5 firmware\$5)) same (integrat\$5	DERWENT;	
		near4 circuit\$5 IC\$2)	IBM TDB	
	1 10			2004/04/10
-	10	1 , 1	USPAT;	2004/04/19
		(updat\$4 upgrad\$5 install\$5 replac\$5)	US-PGPUB;	17:03
		same (printer\$5 near2 (driver\$5 program\$5	EPO; JPO;	
		software\$5 firmware\$5)) same (integrat\$5	DERWENT;	
		near4 circuit\$5 IC\$2)) and @ad<20000929	IBM_TDB	
-	2	("5580177").PN.	USPAT;	2004/04/19
			US-PGPUB;	14:18
			EPO; JPO;	
			DERWENT;	
			IBM TDB	
l <u>-</u>	l o	(2002/0041388).CCLS.	USPAT;	2004/04/19
		, , , , , , , , , , , , , , , , , , , ,	US-PGPUB;	14:18
			EPO; JPO;	- • · • •
			DERWENT;	
1			I	
]	,	2002/0041288	IBM_TDB	2004/04/10
-	1	2002/0041388	USPAT;	2004/04/19
			US-PGPUB;	14:18
Ì			EPO; JPO;	
			DERWENT;	
1			IBM_TDB	
-	0	2002/0041388a1	USPAT;	2004/04/19
			US-PGPUB;	14:18
			EPO; JPO;	
			DERWENT;	
			IBM TDB	
l <u>-</u>	0	20020041388a1	USPAT;	2004/04/19
		2002001130001	US-PGPUB;	14:18
			EPO; JPO;	14.10
			1 '	
			DERWENT;	
		"00000041000"	IBM_TDB	0004/04/10
_	3	"20020041388"	USPAT;	2004/04/19
			US-PGPUB;	14:18
			EPO; JPO;	
}			DERWENT;	
			IBM_TDB	
-	8		USPĀT;	2004/04/19
		("6138178")).PN.	US-PGPUB;	14:19
			EPO; JPO;	
			DERWENT;	
			IBM TDB	
_	2	("6438643").PN.	USPAT;	2004/04/19
		, 1130010 , 11111	US-PGPUB;	14:27
			EPO; JPO;	
			DERWENT;	
			1	
			IBM_TDB	2004/04/10
-	63	pcrd	USPAT;	2004/04/19
			US-PGPUB;	16:48
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	5	(printer\$5 near2 control\$5) same (updat\$4	USPAT;	2004/04/19
1		upgrad\$5 install\$5 replac\$5) same	US-PGPUB;	16:53
		(printer\$5 near2 (driver\$5 program\$5	EPO; JPO;	
		software\$5 firmware\$5)) same (compatibl\$5	DERWENT;	
		integrit\$5 complianc\$5)	IBM TDB	
-	549		USPAT;	2004/04/19
		upgrad\$5 install\$5 replac\$5) same	US-PGPUB;	16:53
		(printer\$5 near2 (driver\$5 program\$5	EPO; JPO;	
		software\$5 firmware\$5))	DERWENT;	
		DOLOWOLOGO LILIMWALGOO!!		
L	<u></u>	I	IBM TDB	





			•	
_	4	(printer\$5 near2 control\$5) same (updat\$4	USPAT;	2004/04/19
		upgrad\$5 install\$5 replac\$5) same	US-PGPUB;	16:54
		(printer\$5 near2 (driver\$5 program\$5	EPO; JPO;	
		software\$5 firmware\$5)) same	DERWENT;	
		(compatibl\$5)	IBM TDB	
1_	34		USPAT;	2004/04/19
]		upgrad\$5 install\$5 replac\$5) same	US-PGPUB;	16:54
		(printer\$5 near2 (driver\$5 program\$5	EPO; JPO;	
ļ		software\$5 firmware\$5)) same (external\$5)	DERWENT;	
		20201132040 222111132040// 221110 (21122113240/	IBM TDB	
l _	16	((printer\$5 near2 control\$5) same	USPAT;	2004/04/19
		(updat\$4 upgrad\$5 install\$5 replac\$5)	US-PGPUB;	17:02
		same (printer\$5 near2 (driver\$5 program\$5	EPO; JPO;	
		software\$5 firmware\$5)) same	DERWENT;	
		(external\$5)) and @ad<20000929	IBM TDB	
 _	17683	(printer\$5 with (print\$5 near2	USPAT;	2004/04/19
	2,000	controller\$5))	US-PGPUB;	17:02
			EPO; JPO;	
			DERWENT;	
			IBM TDB	
_	129	(printer\$5 with (print\$5 near2	USPAT;	2004/04/19
		controller\$5)) same (updat\$4 upgrad\$5	US-PGPUB;	19:25
ľ		install\$5 replac\$5) same (printer\$5 near2	EPO; JPO;	
		(driver\$5 program\$5 software\$5	DERWENT;	
		firmware\$5))	IBM TDB	
_	57		USPĀT;	2004/04/19
		controller\$5)) same (updat\$4 upgrad\$5	US-PGPUB;	17:06
		install\$5 replac\$5) same (printer\$5 near2	EPO; JPO;	
		(driver\$5 program\$5 software\$5	DERWENT;	
		firmware\$5))) and @ad<20000929	IBM TDB	
-	2	("6538762").PN.	USPAT;	2004/04/19
			US-PGPUB;	17:07
			EPO; JPO;	
]			DERWENT;	
			IBM TDB	